

Section V – Reactivity Data

Stability	Unstable		Conditions to Avoid None.
	Stable	X	
Incompatibility (<i>Materials to Avoid</i>) Avoid contact with hot or concentrated nitric and perchloric acids, fuming H ₂ SO ₄ at 60°C (140°F) or above.			
Hazardous Decomposition or Byproducts CO, CO ²			
Hazardous Polymerization	May Occur		Conditions to Avoid None.
	Will Not Occur	X	

Section VI – Health Hazard Data

Route(s) of Entry:	Inhalation? N/A	Skin? N/A	Ingestion? N/A
Health Hazards (<i>Acute and Chronic</i>) None established.			
Carcinogenicity:	NTP? N/A	IARC Monographs? N/A	OSHA Regulated? N/A
Signs and Symptoms of Exposure None.			
Medical Conditions Generally Aggravated by Exposure None.			
Emergency and First Aid Procedures None.			

Section VII – Precautions for Safe Handling and Use

Steps to be Taken in Case Material is Released or Spilled If material is not contaminated, scoop into a clean container for use. If material is contaminated, scoop into container for disposal.	
Waste Disposal Method Sanitary landfill or incinerate mixed with wood or paper waste. Disposal must be done in accordance with local, state and federal regulations.	
Precautions to be Taken in Handling and Storing Store in a sprinklered warehouse. Keep temperature below 60°C (140°F) for quality control.	
Other Precautions None.	

Section VIII – Control Measures

Respiratory Protection (<i>Specific Type</i>) Not required.			
Ventilation	Local Exhaust	Vent process equipment	Special N/A
	Mechanical (<i>General</i>)	over 204°C (400°F)	Other N/A
Protective Gloves Not required.		Eye Protection Safety glasses recommended.	
Other Protective Clothing or Equipment Not required.			
Work/Hygienic Practices In accordance with good housekeeping practices.			

USGPO 1986-491-529/45775